Oil Field Environmental Incident Summary

Responsible Party: Marathon Oil

Well Operator: MARATHON OIL COMPANY

Well Name: WILLIAM USA 31-2H

Field Name: REUNION BAY Well File #: 21466

Date Incident:8/24/2013Time Incident:0820Facility ID Number:County:MOUNTRAILTwp:150Rng:93Sec:2Qtr:

Location Description:

Submitted By: Tonya Woolery Received By:

Contact Person: Tonya Woolery

3172 HWY 22 N

DICKINSON, ND 58601

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Fire

Release Contained in Dike: Yes - Within Dike Reported to NRC: No Units Recovered Spilled Units Followup **Units** Oil 0 barrels 0 barrels 0 barrels 0 barrels **Brine** Other barrels barrels

Description of Other Released Contaminant:

Inspected: Written Report Received: 10/9/2015 Clean Up Concluded: 9/18/2013

Risk Evaluation:

Fire burned itself out. The Rural fire department responded to the incident. They stayed off location and remained on standby.

Areal Extent:

Potential Environmental Impacts:

Impact to water and soil were minimal.

Action Taken or Planned:

Well was shut and all personnel were pulled from location to ensure human safety.

Wastes Disposal Location:

Agencies Involved: Local Fire Department

Updates

Date: 9/3/2013 Status: Reviewed - Assigned to Other Agency Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Fire event. All activity remained inside the diking, according to the report. Location is within MHA Nation. Report forwarded to MHA Environmental and BIA.